
1046,P001USC1

Attorney: Robert A. McLauchlan, Reg. No. 44, 924

1/25 REPLACEMENT SHEET



PRIOR ART



FIG. 1

1046,P001USC1

ceiling joist 22

Robert A. McLauchlan, Reg. No. 44, 924

2/25 REPLACEMENT SHEET hinge 40 pendulum mount 20 support arm drop ceiling 26 top hinge tube 30 base 24

FIG. 24

1046.P001USC1

Robert A. McLauchlan, Reg. No. 44, 924

3/25 REPLACEMENT SHEET




FIG. 2B

Attorney: Robert A. McLauchlan, Reg. No. 44, 924

Filing Date: February 4, 2004 Telephone: (512) 339-4100




FIG. 3A

1046.P001U5C1

Attorney: Robert A. McLauchlan, Reg. No. 44, 924

Filing Date: February 4, 2004 Telephone: (512) 339-4100





FIG. 3B

1046.P001USC1

Attorney: Robert A. McLauchlan, Reg. No. 44, 924



1046.P001USC1

Robert A. McLauchlan, Reg. No. 44, 924

7/25 REPLACEMENT SHEET display 38 pendulum mount 20 support arm 34 positions within arc movable to all tube 30 drop ceiling 26 ceiling joist 22 base 24

1046,P001USC1

Robert A. McLauchlan, Reg. No. 44, 924

Filing Date: February 4, 2004 Telephone: (512) 339-4100





FIG. 6

Attorney: Robert A. McLauchlan, Reg. No. 44, 924

9/25 REPLACEMENT SHEET



Attorney: Robert A. McLauchlan, Reg. No. 44, 924

Filing Date: February 4, 2004 Telephone: (512) 339-4100





FIG. 8A

.

Attorney: Robert A. McLauchlan, Reg. No. 44, 924

Filing Date: February 4, 2004 Telephone: (512) 339-4100



1046.P001USC1

Robert A. McLauchlan, Reg. No. 44, 924

Filing Date: February 4, 2004 Telephone: (512) 339-4100





FIG. 8C

1046.P001U5C1


Attorney: Robert A. McLauchlan, Reg. No. 44, 924

Filing Date: February 4, 2004 Telephone: (512) 339-4100



1046.P001USC1

Attorney: Robert A. McLauchian, Reg. No. 44, 924



1046.P001USC1

Robert A. McLauchlan, Reg. No. 44, 924

Filing Date: February 4, 2004 Telephone: (512) 339-4100





FIG. 11

Attorney: Robert A. McLauchlan, Reg. No. 44, 924

16/25 REPLACEMENT SHEET



:IG. 12

1046,P001USC1

Robert A. McLauchlan, Reg. No. 44, 924

Filing Date: February 4, 2004 Telephone: (512) 339-4100




FIG. 13A

1046.P001USC1

Robert A. McLauchlan, Reg. No. 44, 924

Filing Date: February 4, 2004 Telephone: (512) 339-4100

18/25 REPLACEMENT SHEET

base plate 96




FIG. 13B

1046.P001USC1

Attorney: Robert A. McLauchlan, Reg. No. 44, 924

19/25 REPLACEMENT SHEET




FIG. 14A

1046.P001USC1

Attorney: Robert A. McLauchlan, Reg. No. 44, 924

Filing Date: February 4, 2004 Telephone: (512) 339-4100




FIG. 14B

Attorney: Robert A. McLauchlan, Reg. No. 44, 924

Filing Date: February 4, 2004 Telephone: (512) 339-4100




FIG. 14C

Attorney: Robert A. McLauchlan, Reg. No. 44, 924

Filing Date: February 4, 2004 Telephone: (512) 339-4100




FIG. 15A

1046.P001USC1

Attorney: Robert A. McLauchlan, Reg. No. 44, 924

Filing Date: February 4, 2004 Telephone: (512) 339-4100




FIG. 15B

1046,P001U5C1

Attorney: Robert A. McLauchlan, Reg. No. 44, 924

Filing Date: February 4, 2004 Telephone: (512) 339-4100




FIG. 16A

1046.P001USC1

Robert A. McLauchlan, Reg. No. 44, 924

Filing Date: February 4, 2004 Telephone: (512) 339-4100

base plate 96			
channel 98		\bigcirc	channel 98
Channel 108	0	channel 108	
channel		channel	
108	O	108	
channel 98	channel	98	

FIG. 16B